



Dear Sir,

We have taken trail for 15 days found working satisfactorily. As per our suggestions discharge pipe has been modified by vendor (Photo attached).

Working Parameters as below:

Current amps -14Amps

Discharge head polymer return Line -100Mtr

With Regards

Ravikiran